





Kucina


Vista Frontale




Vista Sotto



Vista dall'Alto



Vista Laterale



| | | |
|---------------------------------------------------------------------------------------------------------|----------|----------|
| Entrata aria comburente / Air Intake Pipe / Entrada de aire comburente/ Entrée d'air/ Primärlufteinlass | A | Ø 130 mm |
| Uscita scarico fumi / Exhaust pipe/ Salida de humos/ Sortie de fumées/ Rauchabzug | B | Ø 80 mm |
| Mandata impianto / Heating Flow / Envío calefacción / Départ chauffage/ Vorlauf | C | 3/4" |
| Ritorno impianto / Heating Return / Retorno calefacción / Retour chauffage/ Rücklauf | F | 3/4" |
| | | |



+39 0968 926838

+39 0968 926857

+39 0444 440963

FAX +39 0968 926861

+39 0444 440963

ASSISTENZA TECNICA CLIENTI

TECHNICAL SUPPORT / ASISTENCIA TÉCNICA CLIENTES

ASSITANCE TECHNIQUE/ TECHNISCHER SERVICE

+39 0968 96484

UNGARO Srl

Via del Progresso, 51

36054 MONTEBELLO VICENTINO (VI) ITALY

info@ungarosrl.com

www.caldoungaro.it